

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES



Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**






FIG. 3




FIG. 2








FIG. 4







NOTE:
REINFS & SIDE INNER
ARE MOLDED TOGETHER

FLOOR ASSEMBLY 321
Fig. 8

REINFORCEMENT
319A

FIXING

SIDE
OUTER
311

REINFORCEMENT BACK ASSEMBLY

BLIND
FIXING

FOAM

SIDE
OUTER

INNER
MOLDING
319B

FIG. 10A

FIXING

INNER
MOLDING

REAR CORNER

WINDOW
OPENING

SIDE INNER
MOLDING

SIDE
OUTER

REINFORCEMENT

FIXING

FOAM

FIG. 10B

TRANSITION
INNER

TRANSITION
OUTER

FRONT
SECTION

FIG. 9

FOAM
339

FIXING

VERTICAL SECTION